



# ORAU TEAM Dose Reconstruction Project for NIOSH

Oak Ridge Associated Universities | Dade Moeller | MJW Technical Services

Page 1 of 23

DOE Review Release 05/03/2010

<b>Document Title:</b> <b>Area IV of the Santa Susana Field Laboratory, the Canoga Avenue Facility, the Downey Facility, and the De Soto Avenue Facility (sometimes referred to as Energy Technology Engineering Center [ETEC] or Atomics International) – Occupational Environmental Dose</b>		<b>Document Number:</b> ORAUT-TKBS-0038-4 <b>Revision:</b> 02 <b>Effective Date:</b> 04/26/2010 <b>Type of Document:</b> TBD <b>Supersedes:</b> Revision 01
<b>Subject Expert(s):</b> Lori Arent and Tracy A. Ikenberry  <b>Site Expert(s):</b> N/A		
<b>Approval:</b>	<u>Signature on File</u> Melton H. Chew, Document Owner	<b>Approval Date:</b> <u>04/16/2010</u>
<b>Concurrence:</b>	<u>Signature on File</u> John M. Byrne, Objective 1 Manager	<b>Concurrence Date:</b> <u>04/16/2010</u>
<b>Concurrence:</b>	<u>Keith A. McCartney Signature on File for</u> Edward F. Maher, Objective 3 Manager	<b>Concurrence Date:</b> <u>04/16/2010</u>
<b>Concurrence:</b>	<u>Signature on File</u> Kate Kimpan, Project Director	<b>Concurrence Date:</b> <u>04/19/2010</u>
<b>Approval:</b>	<u>Signature on File</u> James W. Neton, Associate Director for Science	<b>Approval Date:</b> <u>04/26/2010</u>

New     
  Total Rewrite     
  Revision     
  Page Change

FOR DOCUMENTS MARKED AS A TOTAL REWRITE, REVISION, OR PAGE CHANGE, REPLACE THE PRIOR REVISION AND DISCARD / DESTROY ALL COPIES OF THE PRIOR REVISION.

**PUBLICATION RECORD**

<b>EFFECTIVE DATE</b>	<b>REVISION NUMBER</b>	<b>DESCRIPTION</b>
03/01/2006	00	New technical basis document for the Energy Technology Engineering Center – Occupational Environmental Dose. First approved issue. Initiated by Melton H. Chew.
03/08/2007	01	Approved revision to change the site name throughout the document. Changes site name to Area IV of the Santa Susana Field Laboratory, the Canoga Avenue Facility, the Downey Facility, and the De Soto Avenue Facility (sometimes referred to as Energy Technology Engineering Center [ETEC] or Atomics International. Updated required language in Section 4.1. Purpose section (Section 4.2) and Scope section (Section 4.3) were added. Incorporates internal and NIOSH formal review comments. This revision results in no change to the assigned dose and no PER is required. Training required: As determined by the Task Manager. Initiated by Melton H. Chew.
04/26/2010	02	Revision initiated to incorporate Special Exposure Cohort information in Section 4.1. Incorporates formal internal and NIOSH review comments. Training required: As determined by the Objective Manager. Initiated by Melton H. Chew.

## TABLE OF CONTENTS

<u>SECTION</u>	<u>TITLE</u>	<u>PAGE</u>
	Acronyms and Abbreviations .....	4
4.0	Introduction .....	5
4.1	Special Exposure Cohort Petition information.....	6
4.2	Purpose.....	7
4.3	Scope.....	8
4.4	Operations Overview.....	8
4.5	Inhalation of Onsite Airborne Radionuclides.....	10
4.6	Ambient External Radiation.....	14
4.7	Ingestion .....	17
4.8	Uncertainty.....	18
4.9	Attributions and Annotations.....	18
	References.....	19
	Glossary.....	23

## LIST OF TABLES

<u>TABLE</u>	<u>TITLE</u>	<u>PAGE</u>
4-1	Identified radionuclides in facility air effluents, 1988 to 1999 .....	11
4-2	Annual occupational environmental radionuclide inhalation, Area IV.....	12
4-3	Annual occupational environmental radionuclide inhalation at De Soto Avenue, Canoga Avenue, and Downey facilities. ....	13
4-4	Annual external occupational environmental dose .....	16
4-5	Maximum site-wide median intakes via inadvertent soil ingestion .....	18

**ACRONYMS AND ABBREVIATIONS**

AERD	Atomic Energy Research Department
AI	Atomics International
ATSDR	Agency for Toxic Substances and Disease Registry
Bq	becquerel
Ci	curie
cm	centimeter
DOE	U.S. Department of Energy
dpm	disintegrations per minute
EEOICPA	Energy Employees Occupational Illness Compensation Program Act
ETEC	Energy Technology Engineering Center
GIF	Gamma Irradiation Facility
hr	hour
m	meter
mg	milligram
mrem	millirem
NAA	North American Aviation
NIOSH	National Institute for Occupational Safety and Health
NRC	U.S. Nuclear Regulatory Commission
POC	probability of causation
RIHL	Rockwell International Hot Laboratory (later simply Hot Laboratory)
RMDF	Radioactive Material Disposal Facility
RMHF	Radiation Materials Handling Facility
s	second
SNAP	Systems for Nuclear Auxiliary Power
SRE	Sodium Reactor Experiment
SSFL	Santa Susana Field Laboratory
TBD	technical basis document
TLD	thermoluminescent dosimeter
U.S.C.	United States Code
W	watt
WBNS	Water Boiler Neutron Source
yr	year
§	section

## 4.0 INTRODUCTION

Technical basis documents (TBDs) and site profile documents are not official determinations made by the National Institute for Occupational Safety and Health (NIOSH) but are rather general working documents that provide historic background information and guidance to assist in the preparation of dose reconstructions at particular sites or categories of sites. They will be revised in the event additional relevant information is obtained about the affected site(s). These documents may be used to assist NIOSH staff in the completion of the individual work required for each dose reconstruction.

In this document the word “facility” is used as a general term for an area, building, or group of buildings that served a specific purpose at a site. It does not necessarily connote an “atomic weapons employer facility” or a “Department of Energy [DOE] facility” as defined in the Energy Employees Occupational Illness Compensation Program Act [EEOICPA; 42 U.S.C. § 7384l(5) and (12)]. EEOICPA defines a DOE facility as “any building, structure, or premise, including the grounds upon which such building, structure, or premise is located ... in which operations are, or have been, conducted by, or on behalf of, the Department of Energy (except for buildings, structures, premises, grounds, or operations ... pertaining to the Naval Nuclear Propulsion Program)” [42 U.S.C. § 7384l(12)]. Accordingly, except for the exclusion for the Naval Nuclear Propulsion Program noted above, any facility that performs or performed DOE operations of any nature whatsoever is a DOE facility encompassed by EEOICPA.

For employees of DOE or its contractors with cancer, the DOE facility definition only determines eligibility for a dose reconstruction, which is a prerequisite to a compensation decision (except for members of the Special Exposure Cohort). The compensation decision for cancer claimants is based on a section of the statute entitled “Exposure in the Performance of Duty.” That provision [42 U.S.C. § 7384n(b)] says that an individual with cancer “shall be determined to have sustained that cancer in the performance of duty for purposes of the compensation program if, and only if, the cancer ... was at least as likely as not related to employment at the facility [where the employee worked], as determined in accordance with the POC [probability of causation<sup>1</sup>] guidelines established under subsection (c) ...” [42 U.S.C. § 7384n(b)]. Neither the statute nor the probability of causation guidelines (nor the dose reconstruction regulation, 42 C.F.R. Pt. 82) define “performance of duty” for DOE employees with a covered cancer or restrict the “duty” to nuclear weapons work (NIOSH 2007).

The statute also includes a definition of a DOE facility that excludes “buildings, structures, premises, grounds, or operations covered by Executive Order No. 12344, dated February 1, 1982 (42 U.S.C. 7158 note), pertaining to the Naval Nuclear Propulsion Program” [42 U.S.C. § 7384l(12)]. While this definition excludes Naval Nuclear Propulsion Facilities from being covered under the Act, the section of EEOICPA that deals with the compensation decision for covered employees with cancer [i.e., 42 U.S.C. § 7384n(b), entitled “Exposure in the Performance of Duty”] does not contain such an exclusion. Therefore, the statute requires NIOSH to include all occupationally-derived radiation exposures at covered facilities in its dose reconstructions for employees at DOE facilities, including radiation exposures related to the Naval Nuclear Propulsion Program. As a result, all internal and external occupational radiation exposures are considered valid for inclusion in a dose reconstruction. No efforts are made to determine the eligibility of any fraction of total measured exposure for inclusion in dose reconstruction. NIOSH, however, does not consider the following exposures to be occupationally derived (NIOSH 2007):

- Background radiation, including radiation from naturally occurring radon present in conventional structures
- Radiation from X-rays received in the diagnosis of injuries or illnesses or for therapeutic reasons

<sup>1</sup> The U.S. Department of Labor (DOL) is ultimately responsible under the EEOICPA for determining the POC.

#### **4.1 SPECIAL EXPOSURE COHORT PETITION INFORMATION**

Although NIOSH found that it is not possible to completely reconstruct radiation doses for the SEC classes below, NIOSH intends to use any internal and external monitoring data that may become available for an individual claim (and that can be interpreted using existing NIOSH dose reconstruction processes or procedures). Therefore, dose reconstructions for individuals employed at the Area IV, Canoga Avenue, De Soto Avenue, or Downey facilities during the SEC periods stated below, but who do not qualify for inclusion in the SEC, may be performed using these data as appropriate.

##### **Class Added to the SEC**

###### **Area IV of SSFL (1955-1958)**

- All employees of the Department of Energy (DOE), its predecessor agencies, and DOE contractors and subcontractors who worked in any area of Area IV of the Santa Susana Field Laboratory for a number of work days aggregating at least 250 work days from January 1, 1955 through December 31, 1958, or in combination with work days within the parameters established for one or more other classes of employees in the SEC (Sebelius 2009).

NIOSH determined in 2009 (NIOSH 2009) that it cannot estimate internal exposures with sufficient accuracy during the period from 1955 through 1958. This includes the time from the beginning of Area IV radiological activities in 1955, to late 1958 (selected as December 31, 1958 for SEC evaluation purposes). NIOSH intended the end of the SEC period to correspond with the date after which a routine bioassay program existed at SSFL and after which sufficient internal monitoring was thought to have been identified. Later in 2009 after further data review, NIOSH determined that sufficient data are not available for adequate dose reconstruction until January 1, 1965; NIOSH subsequently initiated a second SEC class for Area IV for the years 1959-1964, as described below.

##### **Classes Recommended by NIOSH for addition to the SEC**

###### **Area IV of SSFL (1959-1964)**

- All employees of the Department of Energy, its predecessor agencies, and their contractors and subcontractors who worked in any area of Area IV of the Santa Susana Field Laboratory from January 1, 1959 through December 31, 1964, for a number of work days aggregating at least 250 work days, occurring either solely under this employment or in combination with work days within the parameters established for one or more other classes of employees included in the Special Exposure Cohort (NIOSH 2010a).

Through the course of ongoing dose reconstruction, continued data capture efforts, and investigations associated with SEC-00093, NIOSH determined in 2010 (NIOSH 2010a) that it cannot estimate with sufficient accuracy the potential internal exposures to various radionuclides to which the proposed class may have been subjected during the time period from January 1, 1959 through December 31, 1964. NIOSH found that it is likely feasible to reconstruct external dose, including occupational medical dose, for Area IV of the Santa Susana Field Laboratory workers with sufficient accuracy.

##### **Canoga Avenue Facility**

- All employees of the Department of Energy, its predecessor agencies, and its contractors and subcontractors who worked at the Canoga Avenue Facility, Los Angeles, California, from January 1, 1955 through December 31, 1960 for a number of work days aggregating at least 250 work days, occurring either solely under this employment or in combination with work days

within the parameters established for one or more other classes of employees in the SEC (NIOSH 2010b).

NIOSH determined in 2010 (NIOSH 2010b) that it cannot estimate internal exposures with sufficient accuracy during the period from 1955 through 1960. This includes the entire covered period for the Canoga Avenue Facility. NIOSH found that it is likely feasible to reconstruct external dose, including occupational medical dose, for Canoga Avenue workers with sufficient accuracy.

### **Downey Facility**

- All employees of the Department of Energy, its predecessor agencies, and their contractors and subcontractors who worked at the Downey Facility in Los Angeles County, California, from January 1, 1948 through December 31, 1955, for a number of work days aggregating at least 250 work days, occurring either solely under this employment or in combination with work days within the parameters established for one or more other classes of employees included in the Special Exposure Cohort (NIOSH 2010c).

NIOSH determined in 2010 (NIOSH 2010c) that it cannot estimate internal exposures with sufficient accuracy during the period from 1948 through 1955. This includes the entire covered period for the Downey Facility so only partial dose reconstructions will be performed for individuals who do not qualify for inclusion in the SEC.

### **De Soto Avenue Facility**

- All employees of the Department of Energy, its predecessor agencies, and their contractors and subcontractors who worked at the De Soto Avenue Facility in Los Angeles County, California, from January 1, 1959 through December 31, 1964, for a number of work days aggregating at least 250 work days, occurring either solely under this employment or in combination with work days within the parameters established for one or more other classes of employees included in the Special Exposure Cohort (NIOSH 2010d).

NIOSH determined in 2010 (NIOSH 2010d) that it cannot estimate internal exposures with sufficient accuracy during the period from 1959 through 1964. The De Soto Avenue Facility has a covered period of DOE 1959-1995 and DOE Remediation 1998. Therefore, dose reconstructions will be performed for 1965 through 1995 and partial dose reconstructions will be performed for individuals who do not qualify for inclusion in the SEC for 1959 through 1964.

## **4.2 PURPOSE**

This document provides a technical basis for evaluating the occupational environmental dose for EEOICPA claimants who were employed at Area IV of the Santa Susana Field Laboratory, Canoga Avenue Facility, Downey Facility, and De Soto Avenue Facility (sometimes referred to as Energy Technology Engineering Center [ETEC] or Atomics International (AI)). Occupational environmental dose refers to radiation exposures received by workers, while on the site but outside the Santa Susana Field Laboratory (SSFL) facilities, from facility discharges to the atmosphere, from ambient external radiation originating in the facilities, and from inadvertent ingestion of site-generated radionuclides. The receptors of concern are SSFL employees who did not wear external dosimetry or who were not monitored for internal exposures.

This facility, which includes four locations, has been identified in various ways over time. SSFL is used to represent all of them unless more specific location information is warranted. In that context, SSFL includes Area IV of the Santa Susana Field Laboratory, which has also been known as Nuclear

Development Field Laboratory; Liquid Metal Engineering Center; Energy Technology Engineering Center (ETEC); portions of the Downey facility; the Canoga Avenue facility; and the De Soto facility.

North American Aviation (NAA) entered into a contract with AEC to conduct nuclear research operations at Area IV and the Downey, Canoga and De Soto sites. At that time, Atomics International, an internal division of NAA, was the company's designated nuclear research and development division. In addition to the employees of the AI division, other employees of NAA who worked at any of the above sites during the AEC contract period are potentially eligible for EEOICPA benefits.

This TBD is part of the overall SSFL Site Profile, which describes plant facilities and processes, historical information, and environmental data in relation to dose reconstruction for SSFL workers. It contains supporting documentation to assist in the evaluation of occupational environmental doses from these processes.

### **4.3 SCOPE**

This TBD describes environmental occupational exposures occurring at the SSFL facilities but outside the occupational workplace. It includes estimated annual intakes of radionuclides from inhalation and inadvertent ingestion and the estimated radiation dose from ambient external exposures from 1952 to 1999. Estimates for different facilities vary by year and by type of exposure since sources of radionuclides and radiation did not exist at all facilities for all years during this period.

### **4.4 OPERATIONS OVERVIEW**

SSFL, operated by The Boeing Company and its predecessors NAA, played an important role in the development of the U.S. nuclear program. SSFL operations involved research, development, and testing of nuclear reactors, nuclear support operations, and non-nuclear energy research and development (Sapere and Boeing 2005, p. 2-2).

From 1948 to 1955, the Atomic Energy Research Department (AERD) of NAA occupied a portion of Building 001 at the Downey facility on Lakewood Boulevard in Downey, California. On April 21, 1952, a small aqueous homogeneous reactor was constructed in an area that is now a loading dock; an environmental monitoring program was apparently initiated during 1952 as well. The reactor and its associated exponential pile were apparently used as a source of neutrons for reactor physics experiments. The Water Boiler Neutron Source (WBNS) used a 93% enriched uranyl sulfate solution and operated at power levels up to 4 W at Downey until December 1955. In 1956, it was dismantled and moved to a facility at the SSFL. Little information is available about the specific uses of the area after the relocation. All available records indicate that the plant was not left in a contaminated condition, and this was confirmed by a survey in 2000 (Liddy and Rutherford 2001). Other radioisotopes used at the Downey facility were apparently for industrial radiography and were not likely a source of internal exposure.

In 1956, NAA formed AI as one of its divisions, replacing AERD. Between 1956 and 1960, nuclear research and development was performed at a facility known as the Canoga Avenue facility, on Canoga Avenue in Canoga Park, California. Two small aqueous 93% enriched uranyl sulfate research reactors designated L-47 and L-77 were designed, developed, and operated at the Canoga Avenue facility. The maximum power ratings were 5 and 10 W, respectively. Other operations included reactor design, fuel development, and radiochemistry. L-47 operated between August 1957 and June 1958, and L-77 operated between May 1958 and February 1960. The reactors were in the southeast corner of the building in what is now a loading dock. Historical information indicates that the areas that supported nuclear operations were routinely surveyed up to and following the removal of all radioactive material. No contamination above the current limits for unrestricted use was found.

This was confirmed by a 1995 survey of the facility by the U.S. Nuclear Regulatory Commission (NRC) (Rutherford 2002). Subsequent occupants of the building would be unlikely to be exposed to contamination levels of importance for internal dose reconstruction.

In 1959, SSFL moved to a new facility on De Soto Avenue in Canoga Park. All radiological activities from the Canoga Avenue facility, including the L-77 reactor, were transferred to the new headquarters facility. Until 1983, nuclear operations were conducted at the De Soto facility in Buildings 101 and 104 (until 1984, these buildings were known as 001 and 004, respectively). Work continued at a much-reduced level in Building 104 until the mid-1990s. The L-77 reactor in Room 416-61 of Building 104 was decommissioned and decontaminated in the late 1970s. The facility was released for unrestricted use in February 1982. Many nuclear fuel manufacturing operations were conducted in the 1960s and 1970s in both Building 101 and Building 104. These operations used 2% to 93% enriched uranium metal and composites.

Two other operations in Building 104 at the De Soto facility used radioactive material. A Gamma Irradiation Facility (GIF) used sealed  $^{137}\text{Cs}$  and  $^{60}\text{Co}$  sources for hardness testing and food irradiation research. Biannual leak tests of these sources confirmed that internal exposures from these devices were unlikely. Operations ceased in the late 1980s; and, following removal of all equipment, the State of California released the GIF for unrestricted use in July 1999. The other Building 104 operation, the Mass Spectroscopy Laboratory or Helium Lab, analyzed radioactive samples for helium content. Operations ceased in 1995 and the mass spectroscopy equipment was sent to Richland, Washington. In 1998, all remaining support equipment was removed and the facility was decontaminated. In October 1998, the State released the Helium Lab for unrestricted use. In all, 13 separate radiation surveys were conducted in Buildings 101 and 104 to demonstrate that no residual contamination existed that would be of interest for dose reconstruction (Boeing 2003).

SSFL consisted of four administrative areas as well as a buffer zone. Area IV was established by NAA at SSFL in 1953 as a nuclear research and development facility<sup>2</sup>. Starting in 1954, several nuclear reactors and critical assemblies were built and operated in Area IV. Nuclear operations (i.e., initial reactor start-up) commenced in 1955. The Agency for Toxic Substances and Disease Registry (ATSDR) investigated radiological incidents occurring at SSFL (ATSDR 1999) and stated: "*Of all these incidents, only the Sodium Reactor Experiment (SRE) Fuel Damage incident, commonly known as "The Meltdown," resulted in a measurable release of radioactive material into the environment.*" The SRE was a sodium-cooled graphite-moderated reactor in Building 143, which in 1959, had a loss of coolant that resulted in damage to 13 fuel assemblies (Sapere and Boeing 2005, pp. 2-1, 2-3, 2-5). Radioactive noble gases reached the outer containment and 28 Ci of radioactive noble gases  $^{133}\text{Xe}$  and  $^{85}\text{Kr}$  were released in a controlled manner and low concentrations to limit the potential dose (Rutherford 2005). A government-owned contractor-operated organization was formed to conduct non-nuclear research at the site. It was renamed ETEC in 1978. Most nuclear research programs and operations ceased in 1988. All research ended in 1998 and decontamination and decommissioning of the former nuclear facilities was begun. Many of the facilities used in Area IV have been decontaminated and decommissioned, but some of the work is ongoing.

For simplicity, the remainder of this document uses SSFL to refer to all of the historical organizations that operated at the De Soto Avenue and Canoga Avenue facilities in Canoga Park, Downey, and Area IV of the SSFL. Activities conducted at all of these SSFL sites and facilities are evaluated in this report.

---

<sup>2</sup> More recently, buildings in Area IV have had the number 4 added to the beginning of the building designation. For example, the original Building 055 would now be referred to as Building 4055.

## 4.5 INHALATION OF ONSITE AIRBORNE RADIONUCLIDES

The environmental monitoring program at Area IV was established in May 1954 before construction of the first radiological facility (Sapere and Boeing 2005, p. 3-13), with emphasis on soil, vegetation, and water sampling in the environment around Area IV. The program had been initiated in 1952 at the Downey Facility but was terminated in the move to Canoga Park (Moore, Fisher, and Rowe 1962). From 1959 to present, ambient gross beta activity in air has been measured continuously in five locations. From 1963 on, gross alpha activity was measured. Ambient air samples are currently analyzed for isotopic content (Sapere and Boeing 2005, p. 3-15). No information is available for the Downey or Canoga Park facilities other than the De Soto facilities; information for the De Soto facilities is not available until ambient data are reported together with Area IV data in environmental monitoring reports. The SSFL ambient air monitoring data through 1999 are reported as gross alpha and gross beta without identification of specific radionuclides. In all cases, the gross alpha and gross beta concentrations are a small fraction of the applicable limits and are indistinguishable from background. Because of this, stack emission data were used as the primary basis for inhalation intake estimates from onsite atmospheric radionuclide concentrations.

Average annual gross alpha/gross beta concentrations in facility stack emissions were the basis for estimating potential worker environmental inhalation intakes. Most of the available SSFL stack emission data include annual average gross alpha and gross beta concentrations at the stack point of release. Years with data vary by facility, but gross alpha/gross beta concentration information is available for most years between 1971 and 1999. For years where there were no emission data, the facility-specific average for available years was used. The average of yearly data was used rather than the median because the average concentration was higher. In many cases, the stack emission concentrations of gross alpha and gross beta are indistinguishable from the ambient background concentrations, indicating manmade radionuclide releases were very low.

Identification of specific radionuclides released from various facilities in stack emissions are available in data from 1988 to 1999 and were used to characterize radionuclide emissions for all years. There are no radionuclide-specific data from earlier years. The radionuclide-specific data showed that naturally occurring radionuclides were major constituents of radionuclide emissions, with  $^{210}\text{Po}$  a main constituent of the gross alpha concentration and  $^{40}\text{K}$  and  $^7\text{Be}$  major constituents of the gross beta detected. Any uranium and thorium detected is assumed to originate from facility activities, even though it could be naturally occurring.

### 4.5.1 Stack Effluent Concentrations, 1988 to 1999

Radionuclide-specific gross alpha and gross beta stack emission data are available for this period for some facilities. In Area IV, these facilities include mainly Building 020<sup>3</sup> (Rockwell International Hot Laboratory [RIHL], later known as simply Hot Laboratory) and Buildings 021-022 (Radioactive Materials Disposal Facility [RMDF], Radioactive Materials Handling Facility [RMHF]), with limited information for T024 (Systems for Nuclear Auxiliary Power [SNAP] Environmental Test Facility), and T059 (SNAP 8 Development Reactor) (Moore 1989; Robinson 1998; Gaylord 1990; Rutherford 1999; Rockwell 1991, 1992, 1993, 1996; Boeing 2000; Tuttle 1997).

For De Soto, the only facility for which there is emission data is Building 004/104 (Hot Analytical Chemistry). The most complete information and the majority of the radioactive releases come from Building 020 for Area IV. These effluent data show that the majority of the release during most years was from naturally occurring radionuclides:  $^{210}\text{Po}$  for alpha-emitters and  $^{40}\text{K}$  and  $^7\text{Be}$  for beta-emitters. No data were available for 1993 and 1994.

<sup>3</sup> As noted in an earlier footnote, the original Building 020 may be referred to as Building 4020.

Table 4-1 lists the radionuclides identified as being released from each facility during this period. Naturally occurring radionuclides are not included; isotopes of thorium and uranium could be naturally occurring but are not so considered in effluent reports.

Table 4-1. Identified radionuclides in facility air effluents, 1988 to 1999.

Facility	Alpha emitters	Beta emitters
020, Hot Lab	Pu-238, Pu-239, U-234, U-235, U-238, Th-228, Th-230, Th-232, Am-241	Co-60, Sr-90, Cs-137
021-022, RMDf/RMHF	Pu-238, Pu-239, U-234, U-235, U-238, Th-228, Th-230, Th-232, Am -241	Co-60, Sr-90, Cs-137, H-3
T024, SNAP ETF	Th-230	Cs-137
T059, SNAP8DR	Pu-238, Pu-239, U-234, U-238, Am-241	Co-60, Cs-137
004/104, De Soto	Pu-238, Pu-239, U-234, U-235, U-238, Th-228, Th-230, Th-232, Am -241	Co-60, Sr-90, Cs-137, Pu-241

#### **4.5.2 Stack Effluent Concentrations, 1971 to 1987**

Gross alpha and gross beta effluent data are available for most years during this period for Area IV facilities Buildings 020, 021-022, and 055 (Nuclear Materials Development Facility), and limited data is available for Building 003 (Engineering Test Building) (Remley 1979, Eggleston 1983, 1984; Hart 1979; Hart 1980a; Hart 1980b; Hart 1980c; Hart 1980d; Moore c. 1974; Heine 1973; Oldenkamp and Mills 1991; Tuttle 1985, 1986a, 1986b, 1986c, 1988a, 1988b).

Data are available for De Soto Building 004/104 and 001/101 (Fuel Fabrication). Because of lack of other information, Building 001/101 was assumed to have the same radionuclide composition in effluents as Building 004/104. This is a conservative assumption because, as a fuel fabrication facility, no mixed fission products would be expected in the gross beta emissions. In years where data were not available, stack concentrations were assumed to be the average yearly gross alpha and gross beta concentrations in stack effluents from years 1971 to 1999, for which data were available.

#### **4.5.3 Stack Effluent Concentrations, 1959 to 1970**

No data were available for this period, but because operations and activities during this period took place in many of the same facilities addressed in later years, the average yearly gross alpha and gross beta concentrations in stack effluents from 1971 to 1999 were assumed for each of these years. Furthermore, the average percentage that each identified radionuclide contributed to the gross alpha or gross beta concentration determined from 1988 to 1999 data was applied to each of these years to make radionuclide-specific stack concentration estimates. Because no radionuclide-specific data were available for Building 055, the characteristic effluent radionuclide percentage from Buildings 024 and 059 were applied. Radionuclide-specific data were also unavailable for De Soto Building 001/101, so the characteristic effluent radionuclides percentages from Building 004/104 were applied.

#### **4.5.4 Stack Effluent Concentrations, Before 1959**

No data are available for the period before 1959; the facilities operating during this period were mainly small reactor facilities. The SRE, the largest reactor at SSFL, operated from 1957 to 1964 in Area IV. It is possible that reactor operations before 1959 could have released fission product activities similar to those after 1959. Therefore, fission product releases from Area IV from 1954 to 1958 are assumed to be the same as 1959 to 1964. There would have been few activities or operations with potential for release of alpha-emitting radionuclides; therefore, alpha-emitting radionuclides from 1954 to 1958 are assumed to be 10 percent of alpha-emitting radionuclide releases from 1959 to 1964. Operations at the De Soto Avenue facilities did not begin until 1959. Activities at the Downey site from 1952 to 1955

and Canoga Park facility from 1954 to 1960 were limited and releases are conservatively assumed to be the same as the 1954 Area IV releases.

#### 4.5.5 Estimates of Potential Inhalation Intake, 1952 to 1999

The average annual stack effluent concentrations described in Section 4.6.3 were used as the basis for estimating occupational environmental inhalation intakes from facility effluent releases. The facility effluent concentrations for each year were summed. Workers were assumed to be exposed for 2,000 hr/yr with a breathing rate of  $3.3 \times 10^{-4} \text{ m}^3/\text{s}$  (ICRP 1975). Because the stack effluent concentrations were at the point of release, a further reduction factor of 0.01 was taken to account for the lessened overall intake due to contribution from multiple, widely spaced facilities; atmospheric dispersion of stack effluent over the course of a year's exposure; and building wake effects.

Noble gases are not included in the estimates of intake because they are not included in emission monitoring data and because the potential dose from radioactive noble gases is very small. In addition and with one exception, acute release events that contribute negligibly to the annual average radionuclide concentration are not included. The exception is the inclusion of mixed fission product releases from a burned fuel slug event occurring in Building 020 in July 1975, which had a noticeable effect on the average annual gross beta concentrations (Hart 1979).

Table 4-2 lists the estimated environmental inhalation intakes in Area IV. Table 4-3 lists the estimated environmental inhalation intakes at the Canoga Park De Soto Avenue and Canoga Avenue facilities and the Downey site. In the absence of measurements or studies, NIOSH guidance requires that default solubility classes and particle size values from the International Commission on Radiological Protection be used (NIOSH 2002, pp. 15–16). Facility-specific solubility and particle size data are not available. The most favorable to claimant material form and solubility should be selected for each radionuclide at all sites and facilities.

Table 4-2. Annual occupational environmental radionuclide inhalation, Area IV (Bq/yr).

Year	Radionuclide												
	Pu-239	Pu-238	Am-241	U-234	U-235	U-238	Th-228	Th-232	Th-230	Co-60	Sr-90	Cs-137	H-3
1999	1.1E-04	2.4E-06	6.4E-06	2.0E-04	4.1E-06	4.7E-04	8.0E-06	9.1E-06	1.8E-03	1.1E-02	3.0E-02	9.0E-02	2.1E-02
1998	5.3E-04	4.2E-05	1.4E-05	5.7E-04	3.0E-05	7.7E-04	5.8E-05	1.2E-04	4.3E-03	3.5E-02	3.1E-02	1.4E-01	2.3E-01
1997	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	4.9E-03	1.1E-03	8.1E-03	2.9E-01
1996	6.5E-05	2.0E-06	5.7E-06	1.3E-04	4.9E-06	4.9E-04	9.6E-06	9.2E-06	6.1E-04	6.3E-03	1.3E-03	1.4E-02	1.9E-01
1995	1.9E-04	1.0E-05	1.6E-05	3.3E-04	1.8E-05	1.5E-03	3.5E-05	4.0E-05	6.3E-04	8.3E-03	2.7E-03	2.0E-02	2.9E-01
1994	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1993	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1992	9.8E-05	7.9E-06	6.0E-06	1.3E-04	9.2E-06	5.2E-04	1.8E-05	2.6E-05	1.6E-04	1.9E-03	7.0E-04	4.1E-02	9.3E-02
1991	2.1E-04	1.7E-05	1.0E-05	2.6E-04	1.7E-05	8.0E-04	3.3E-05	5.2E-05	8.9E-04	5.4E-03	1.5E-03	1.3E-02	1.7E-01
1990	1.4E-04	7.6E-06	1.1E-05	2.3E-04	1.2E-05	9.7E-04	2.5E-05	2.9E-05	6.3E-04	4.4E-03	8.5E-04	1.1E-02	7.4E-02
1989	3.3E-05	1.1E-06	1.1E-06	5.2E-05	6.6E-07	5.5E-05	1.3E-06	2.8E-06	6.1E-04	5.6E-03	5.1E-04	1.1E-02	1.5E-01
1988	1.2E-04	1.0E-05	3.6E-06	1.2E-04	8.1E-06	2.5E-04	1.6E-05	3.0E-05	6.5E-04	7.2E-03	1.2E-03	1.5E-02	2.4E-01
1987	6.5E-05	3.9E-06	2.9E-06	9.1E-05	3.8E-06	2.1E-04	7.4E-06	1.2E-05	6.2E-04	1.5E-02	2.5E-03	2.7E-02	7.2E-01
1986	5.6E-05	5.2E-06	1.9E-06	5.6E-05	4.3E-06	1.4E-04	8.4E-06	1.5E-05	1.8E-04	1.5E-02	4.2E-03	3.4E-02	5.6E-01
1985	1.2E-04	8.2E-06	9.2E-06	1.8E-04	1.2E-05	8.2E-04	2.3E-05	2.9E-05	1.3E-04	1.5E-02	2.1E-02	7.0E-02	5.5E-01
1984	7.7E-05	8.0E-06	2.3E-06	6.7E-05	6.3E-06	1.7E-04	1.2E-05	2.3E-05	1.0E-04	1.0E-03	8.2E-04	3.9E-03	1.6E-02
1983	4.9E-05	4.9E-06	1.0E-06	4.2E-05	3.4E-06	6.1E-05	6.7E-06	1.4E-05	1.9E-04	1.5E-03	3.7E-04	3.5E-03	4.8E-02
1982	2.0E-04	2.3E-05	2.4E-06	1.2E-04	1.5E-05	1.0E-04	3.0E-05	6.4E-05	1.4E-04	1.8E-03	2.7E-03	9.6E-03	2.5E-02
1981	8.4E-05	8.9E-06	2.0E-06	6.9E-05	6.6E-06	1.3E-04	1.3E-05	2.5E-05	1.7E-04	4.9E-03	3.0E-03	1.5E-02	1.7E-01
1980	2.1E-04	1.4E-05	6.9E-06	2.7E-04	1.0E-05	4.3E-04	2.0E-05	3.8E-05	2.3E-03	9.6E-03	3.2E-03	2.5E-02	2.3E-01
1979	1.3E-04	1.3E-05	3.3E-06	1.0E-04	1.0E-05	2.3E-04	2.0E-05	3.8E-05	1.9E-04	5.3E-03	6.2E-03	2.1E-02	2.3E-01
1978	1.1E-04	1.1E-05	3.0E-06	9.3E-05	8.4E-06	2.2E-04	1.7E-05	3.1E-05	2.0E-04	1.3E-02	9.2E-03	4.1E-02	4.9E-01
1977	1.3E-04	1.4E-05	2.2E-06	8.9E-05	9.6E-06	1.2E-04	1.9E-05	3.8E-05	2.1E-04	5.9E-03	1.7E-03	1.5E-02	1.6E-01
1976	2.4E-04	2.8E-05	3.7E-06	1.6E-04	1.9E-05	1.9E-04	3.7E-05	7.7E-05	2.7E-04	4.0E-03	6.9E-04	1.0E-02	5.1E-02
1975	4.7E-04	5.5E-05	5.9E-06	2.9E-04	3.6E-05	2.6E-04	7.1E-05	1.5E-04	4.1E-04	1.6E-01	6.1E-01	1.7E+00	5.1E-01
1974	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1973	1.6E-04	1.7E-05	3.8E-06	1.3E-04	1.3E-05	2.6E-04	2.5E-05	4.9E-05	2.1E-04	3.9E-03	1.3E-03	7.5E-03	2.3E-01
1972	1.6E-04	1.6E-05	4.8E-06	1.4E-04	1.3E-05	3.6E-04	2.6E-05	4.7E-05	2.2E-04	1.0E-02	3.0E-02	8.7E-02	6.2E-02

1971	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1970	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1969	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1968	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1967	1.6E-04	1.4E-05	5.4E-06	1.6E-04	1.1E-05	3.9E-04	2.2E-05	4.0E-05	6.6E-04	1.4E-02	3.1E-02	9.5E-02	2.3E-01
1966	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1965	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1964	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1963	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1962	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1961	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1960	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1959	1.3E-04	1.4E-05	4.4E-06	1.2E-04	1.1E-05	3.4E-04	2.2E-05	4.0E-05	5.1E-05	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1958	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1957	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1956	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1955	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01
1954	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01

Table 4-3. Annual occupational environmental radionuclide inhalation at De Soto Avenue, Canoga Avenue, and Downey facilities (Bq/yr).

Year	Radionuclide												
	Pu-239	Pu-238	Am-241	U-234	U-235	U-238	Th-228	Th-232	Th-230	Co-60	Sr-90	Cs-137	Pu-241
1954-1999, De Soto Avenue													
1999	0	0	0	0	0	0	0	0	0	0	0	0	0
1998	9.1E-07	1.1E-05	2.6E-05	2.1E-04	1.4E-05	2.6E-05	1.1E-04	4.0E-05	4.5E-05	3.9E-05	3.6E-04	1.8E-04	0
1997	3.7E-06	4.3E-05	1.1E-04	8.6E-04	5.6E-05	1.1E-04	4.4E-04	1.6E-04	1.8E-04	3.4E-05	3.1E-04	1.5E-04	0
1996	1.8E-07	2.1E-06	5.0E-06	4.1E-05	2.7E-06	5.0E-06	2.1E-05	7.8E-06	8.7E-06	1.1E-05	1.0E-04	4.9E-05	0
1995	3.6E-07	4.2E-06	1.0E-05	8.4E-05	5.5E-06	1.0E-05	4.3E-05	1.6E-05	1.8E-05	1.9E-05	1.7E-04	8.4E-05	6.5E-03
1994	7.6E-06	8.9E-05	2.2E-04	1.8E-03	1.2E-04	2.2E-04	9.1E-04	3.3E-04	3.7E-04	5.1E-05	4.8E-04	2.3E-04	0
1993	7.6E-06	8.9E-05	2.2E-04	1.8E-03	1.2E-04	2.2E-04	9.1E-04	3.3E-04	3.7E-04	5.1E-05	4.8E-04	2.3E-04	0
1992	1.4E-06	1.6E-05	4.0E-05	3.2E-04	2.1E-05	3.9E-05	1.7E-04	6.1E-05	6.8E-05	2.6E-05	2.4E-04	1.2E-04	0
1991	1.2E-06	1.4E-05	3.4E-05	2.8E-04	1.8E-05	3.4E-05	1.4E-04	5.3E-05	5.9E-05	4.9E-05	4.6E-04	2.2E-04	0
1990	1.8E-06	2.1E-05	5.1E-05	4.2E-04	2.7E-05	5.1E-05	2.1E-04	7.9E-05	8.8E-05	9.5E-05	8.9E-04	4.3E-04	0
1989	7.6E-06	8.9E-05	2.2E-04	1.8E-03	1.2E-04	2.2E-04	9.1E-04	3.3E-04	3.7E-04	5.1E-05	4.8E-04	2.3E-04	0
1988	4.2E-06	4.9E-05	1.2E-04	9.8E-04	6.4E-05	1.2E-04	5.0E-04	1.9E-04	2.1E-04	6.8E-05	6.4E-04	3.1E-04	0
1987	5.2E-06	6.1E-05	1.5E-04	1.2E-03	7.9E-05	1.5E-04	6.2E-04	2.3E-04	2.6E-04	4.9E-05	4.6E-04	2.2E-04	0
1986	1.4E-06	1.6E-05	4.0E-05	3.2E-04	2.1E-05	4.0E-05	1.7E-04	6.2E-05	6.9E-05	5.8E-05	5.4E-04	2.6E-04	0
1985	3.3E-06	3.9E-05	9.5E-05	7.7E-04	5.1E-05	9.5E-05	4.0E-04	1.5E-04	1.6E-04	4.2E-05	3.9E-04	1.9E-04	0
1984	1.0E-05	1.2E-04	3.0E-04	2.4E-03	1.6E-04	2.9E-04	1.2E-03	4.5E-04	5.1E-04	5.5E-05	5.1E-04	2.5E-04	0
1983	4.5E-04	5.3E-03	1.3E-02	1.0E-01	6.8E-03	1.3E-02	5.4E-02	2.0E-02	2.2E-02	6.6E-04	6.2E-03	3.0E-03	0
1982	1.0E-05	1.2E-04	2.9E-04	2.3E-03	1.5E-04	2.9E-04	1.2E-03	4.5E-04	5.0E-04	4.7E-05	4.4E-04	2.2E-04	0
1981	2.2E-05	2.6E-04	6.3E-04	5.1E-03	3.3E-04	6.3E-04	2.6E-03	9.7E-04	1.1E-03	1.4E-04	1.3E-03	6.3E-04	0
1980	3.9E-06	4.6E-05	1.1E-04	9.1E-04	6.0E-05	1.1E-04	4.7E-04	1.7E-04	1.9E-04	1.9E-04	1.8E-03	8.6E-04	0
1979	1.8E-04	2.1E-03	5.0E-03	4.1E-02	2.7E-03	5.0E-03	2.1E-02	7.8E-03	8.7E-03	2.0E-04	1.8E-03	8.9E-04	0
1978	2.6E-06	3.0E-05	7.5E-05	6.0E-04	4.0E-05	7.4E-05	3.1E-04	1.1E-04	1.3E-04	1.3E-04	1.2E-03	5.7E-04	0
1977	2.2E-06	2.6E-05	6.2E-05	5.1E-04	3.3E-05	6.2E-05	2.6E-04	9.6E-05	1.1E-04	1.2E-04	1.1E-03	5.3E-04	0
1976	3.0E-04	3.5E-03	8.5E-03	6.9E-02	4.5E-03	8.5E-03	3.6E-02	1.3E-02	1.5E-02	3.6E-04	3.4E-03	1.6E-03	0
1975	2.4E-05	2.8E-04	6.9E-04	5.6E-03	3.7E-04	6.9E-04	2.9E-03	1.1E-03	1.2E-03	1.2E-04	1.1E-03	5.4E-04	0
1974	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1973	9.7E-06	1.1E-04	2.8E-04	2.2E-03	1.5E-04	2.8E-04	1.2E-03	4.3E-04	4.8E-04	7.7E-05	7.2E-04	3.5E-04	0
1972	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1971	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1970	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1969	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1968	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1967	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1966	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1965	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1964	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1963	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1962	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1961	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1960	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1959	9.4E-05	1.1E-03	2.7E-03	2.2E-02	1.4E-03	2.7E-03	1.1E-02	4.1E-03	4.6E-03	1.9E-04	1.8E-03	8.9E-04	0
1954-1960, Canoga Avenue (all years are the same)													<b>H-3</b>
All	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01

Year	Radionuclide												
	Pu-239	Pu-238	Am-241	U-234	U-235	U-238	Th-228	Th-232	Th-230	Co-60	Sr-90	Cs-137	Pu-241
	1954-1999, De Soto Avenue												
	1952-1955, Downey Site (all years are the same)												H-3
All	1.3E-05	1.4E-06	4.4E-07	1.2E-05	1.1E-06	3.4E-05	2.2E-06	4.0E-06	5.1E-06	1.1E-02	3.1E-02	8.8E-02	2.3E-01

## 4.6 AMBIENT EXTERNAL RADIATION

Ambient external radiation dose information for SSFL is available for 1975 to 1999. During the later years (1974 to 1989) of the active nuclear programs at SSFL, the ambient radiation monitoring program used complex bulb dosimeters (CaF<sub>2</sub>:Mn). This was justified by the amount of nuclear materials handled in the operations in Area IV and De Soto and by the low levels of radiation in the environment. At the termination of all nuclear work in 1989, that level of monitoring was no longer needed and efforts were directed toward simplifying the program. The initial step included using the well-established LiF thermoluminescent dosimeters (TLDs) for personnel monitoring in radiation work. While these dosimeters were well suited to measuring exposures in the range of interest for compliance with occupational radiation regulations (doses above background), they were somewhat insensitive for environmental measurements because the resolution in terms of dose uses increments of 10 mrem/quarter. Using these dosimeters demonstrated that environmental exposures did not reach regulatory limits, but it provided limited information on the actual exposure rates around the facilities and in the neighboring environment (Rutherford 1999).

In addition to the LiF TLDs, in the last quarter of 1995, deployment of environmental TLDs that used an aluminum oxide (called *sapphire*) chip began. These TLDs were capable of determining doses in increments of 0.1 mrem (in comparison to 10 mrem for the LiF badges). Proper use of the control badges supplied with these dosimeters allowed elimination of the natural and transportation exposure that occurred before, during, and after the deployment of the environmental dosimeters to measure the ambient radiation. This permitted accurate determination of the net exposure received while the environmental TLDs were exposed in the field to the ambient radiation (Rutherford 1999).

The following sections describe estimates of environmental external dose during five periods from 1954 to 1999; estimates for possible earlier exposures in Downey and Canoga Park are also provided. Workers were assumed to be exposed for 2,000 hr/yr. A baseline estimate of the environmental external dose was developed for each period, and additional dose for specific facilities during specific years was developed based on aerial survey information and specific facility fence line exposure rate information. In all cases, the minimum dose above background is 10 mrem/yr.

### 4.6.1 External Dose, 1996 to 1999

The sensitivity of the aluminum oxide chip in environmental TLDs is accounted for during this period. Average annual dose from offsite background dosimeters is subtracted from the average annual dose of environmental TLDs in Area IV and De Soto to provide an estimate of the baseline occupational environmental dose at the respective sites. The baseline occupational environmental dose for both De Soto and Area IV is 10 mrem/yr. In addition, environmental dosimeters near Buildings 021-022 (RMDF/RMHF) are consistently higher than the average. This is stated to be reflective of normal operations at the RMHF (Rutherford 1999). Occupational environmental doses near this facility are increased by 10 mrem/yr during this period to 20 mrem/yr.

### 4.6.2 External Dose, 1990 to 1995

Relatively insensitive LiF chips were used in dosimeters during this period, so the baseline dose during this period was based on the minimum dosimeter sensitivity of 10 mrem/quarter or 40 mrem/yr. This minimum sensitivity baseline results in a higher annual dose than subtraction of offsite

background dose from onsite environmental dosimeter results. The occupational environmental external dose near Buildings 021-022 is increased by 10 mrem/yr because of elevated dosimeter readings.

#### **4.6.3 External Dose, 1975 to 1989**

External doses during this period of active nuclear operations at SSFL were measured using the complicated  $\text{CaF}_2:\text{Mn}$  bulb dosimeters. Baseline external occupational environmental doses during this period were estimated by subtracting the average annual offsite background dose from the maximum annual onsite dose at De Soto and Area IV. Baseline doses were at the minimum of 10 mrem/yr except for 1978, when radiation from the Building 621 area (described below) was high enough that the baseline dose for the site was doubled to 20 mrem/yr.

Three documents provided quarterly facility fence line exposure rates for Building 20 (RIHL) and Buildings 021-022 (RMDF/RMHF) during 1986, 1987, and 1988 (Tuttle 1988a, 1988b, 1989). These measurements showed the exposure rates around Building 020 to be background, but the exposure rates around the RMDF to be elevated above the baseline. These measurements were used as the basis for elevating external occupational environmental doses around the RMDF along with results of an aerial radiological survey in 1978 (Jobst 1979). The aerial survey represents a snapshot in time, but shows elevated exposure rates around the RMDF; around Building 143, the SRE facility, from storage of radioactive material; and around the Building 621, Radioactive Accountable Waste Storage Building, from storage of radioactive liquid in a nearby tank vault. Because of the nature of the survey, these elevated exposure rates were applied only to the year 1978 for the SRE facility. However, because elevated exposure around the RMDF had occurred in other years, the aerial survey results were included in determining an average elevated dose rate for the RMDF. Because Building 621 was part of the RMDF complex, the RMDF elevated results were applied throughout this period to Building 621 as well.

#### **4.6.4 External Dose, 1959 to 1974**

No data are available for the period from 1959 to 1974, but many of the same nuclear operations continued during this period. The facilities not considered are mainly small reactor facilities, which are typically well-shielded. The SRE, the largest reactor at SSFL, operated from 1957 to 1964. Building 621 was constructed in the mid-1960s (Sapere and Boeing 2005, Volume 2, Part 5). Both Building 020, the Hot Lab, and Buildings 021-022, the RMDF, began operations in 1959. Based on operating information from 1975 to 1989, estimates were made of the occupational environmental external dose for 1959 to 1974. The baseline dose above background in Area IV was assumed to be doubled to 20 mrem/yr to account for reactor operations during this period. The baseline dose in De Soto remains at 10 mrem/yr. Facility-specific dose during these years was assumed to be elevated to 20 mrem/yr for De Soto Building 001 and elevated to 80 mrem/yr for the RMDF in Area IV. During the years of SRE operations, a facility-specific dose of 40 mrem/yr was assumed for Building 143.

#### **4.6.5 External Dose Before 1959**

No data are available for the period before 1959. As noted above, the facilities were mainly small reactor facilities, which are typically well-shielded. The SRE, the largest reactor at SSFL, operated from 1957 to 1964 in Area IV. The baseline dose above background in Area IV was assumed to be 20 mrem/yr to account for reactor operations during this period. The facility-specific dose for Building 143 was 40 mrem/yr for 1954 to 1959. Environmental external doses from 1952 to 1955 for Downey and from 1954 to 1960 for the Canoga Park facility are estimated to be 10 mrem/yr based on the operation of small test reactors.

#### 4.6.6 Estimates of External Dose, 1952 to 1999

Table 4-4 lists the occupational environmental external dose estimates for Area IV, De Soto Avenue, Canoga Avenue, and Downey sites for applicable periods from 1952 to 1999. Some facility-specific doses are provided for De Soto and in Area IV.

Table 4-4. Annual external occupational environmental dose (mrem/yr).

Year	De Soto		Area IV			
	Baseline <sup>a</sup>	Facility-specific dose	Baseline <sup>a</sup>	Facility-specific dose		
		Fuel Fab Bldg 001		RMDF Bldg 021-022	SRE Bldg 143	RAWBS Bldg 621
1999	N/A	N/A	10	20	N/A	N/A
1998	10	N/A	10	20	N/A	N/A
1997	10	N/A	10	20	N/A	N/A
1996	10	N/A	10	20	N/A	N/A
1995	40	N/A	40	50	N/A	N/A
1994	40	N/A	40	50	N/A	N/A
1993	40	N/A	40	50	N/A	N/A
1992	40	N/A	40	50	N/A	N/A
1991	40	N/A	40	50	N/A	N/A
1990	40	N/A	40	50	N/A	N/A
1989	10	N/A	10	20	N/A	20
1988	10	N/A	10	40	N/A	40
1987	10	N/A	10	60	N/A	60
1986	10	N/A	10	160	N/A	160
1985	10	N/A	10	70	N/A	70
1984	10	N/A	10	70	N/A	70
1983	10	20	10	70	N/A	70
1982	10	20	10	70	N/A	70
1981	10	20	10	70	N/A	70
1980	10	20	10	70	N/A	70
1979	10	20	10	70	N/A	70
1978	10	20	20	40	90	180
1977	10	20	10	70	N/A	70
1976	10	20	10	70	N/A	70
1975	10	20	10	70	N/A	70
1974	10	20	20	80	N/A	80
1973	10	20	20	80	N/A	80
1972	10	20	20	80	N/A	80
1971	10	20	20	80	N/A	80
1970	10	20	20	80	N/A	80
1969	10	20	20	80	N/A	80
1968	10	20	20	80	N/A	80
1967	10	20	20	80	N/A	80
1966	10	20	20	80	N/A	80
1965	10	20	20	80	N/A	N/A
1964	10	20	20	80	40	N/A
1963	10	20	20	80	40	N/A
1962	10	20	20	80	40	N/A
1961	10	20	20	80	40	N/A
1960	10	20	20	80	40	N/A
1959	10	20	20	80	40	N/A
1958	N/A	N/A	20	N/A	40	N/A
1957	N/A	N/A	20	N/A	40	N/A
1956	N/A	N/A	20	N/A	N/A	N/A
1955	N/A	N/A	20	N/A	N/A	N/A
1954	N/A	N/A	20	N/A	N/A	N/A
<b>Canoga Avenue</b>						
1954-1960	10					
<b>Downey</b>						
1952-1955	10					

a. Minimum above-background baseline external dose of 10 mrem/yr.

#### 4.7 INGESTION

Two sources of occupationally derived radioactive material for ingestion are possible:

- Potable water
- Removable surface contamination from floors, objects, or soils via the hand to the mouth

Potable water is not a source of occupational radioactive material at SSFL because the SSFL facilities used either bottled water from an offsite vendor (Moore, Fisher, and Rowe 1962) or the city water supply. SSFL continues to use bottled water.

Ingestion of removable surface contamination is negligible because the intake is proportional to the amount of dirt consumed. In NRC NUREG/CR-5512, Kennedy et al. (1992, p. 6.14) assumes the amount of soil ingested by an adult involved in building renovation work would be 10 mg/hr. More sedentary work would produce a smaller consumption, perhaps 50 mg/day. The other factor is the activity concentration in the ingested dirt. It is reasonable to expect that, outside of radiologically controlled areas, the removable surface contamination level or activity concentration in soil should on average approach background levels. The surface contamination level is unlikely to average an order of magnitude more than the background level for the entire workplace for the entire year.

Kennedy et al. (1992, Sections 3.2.5 and 6.3.2) define methods and assumptions for use in calculation of doses to individuals occupying a facility contaminated with residual radioactive material. An equation for calculation of ingestion dose is included. For purposes of EEIOCPA, dose is reconstructed by different algorithms than those used in this report, so only the ingestion intake is estimated here.

The method equation can be summarized in a word description as:

*Intake equals the exposure duration multiplied by the effective transfer rate of removable contamination from surface to hands then to mouth and multiplied by the average removable surface contamination level.*

More specifically:

$$Ingestion = t \times GO \times Act$$

where

*Ingestion* = ingestion intake in Bq/yr;  
*t* = annual exposure duration (2,000 hr/yr);  
*GO* = ingestion transfer rate of removable surface activity during building occupancy ( $1 \times 10^{-4}$  m<sup>2</sup>/hr);  
*Act* = removable surface contamination (activity) level (Bq/m<sup>2</sup>).

Therefore, full-time occupancy (2,000 hr/yr) in an area with a removable surface activity of a radionuclide at the level of 1 Bq/m<sup>2</sup> would result in an intake of 0.2 Bq of that radionuclide per year.

Inadequate data are available to estimate the median ingestion each year and at each facility, but estimates or bounding assumptions are necessary for dose reconstruction. To conservatively bound ingestion from occupational environmental sources, a worker is assumed to be a full-time occupant (2,000 hr/yr) of an area contaminated with <sup>239</sup>Pu and <sup>90</sup>Sr at 100% of their current removable

contamination limits. These NRC-defined contamination limits (AEC 1974) have been essentially unchanged for decades. The plutonium limit is 20 dpm/100 cm<sup>2</sup> or 33 Bq/m<sup>2</sup>, the strontium limit is 200 dpm/100 cm<sup>2</sup> or 330 Bq/m<sup>2</sup>. The resultant ingestion intake for all years and all SSFL facilities is bounded at a level of 6.7 Bq/yr of <sup>239</sup>Pu and 67 Bq/yr of <sup>90</sup>Sr, as shown in Table 4-5. The most favorable to claimant material form and solubility should be selected for each radionuclide.

Table 4-5. Maximum site-wide median intakes (Bq/yr) via inadvertent soil ingestion.

Site	Years	Radionuclide <sup>a</sup>	
		Pu-239	Sr-90
Area IV	1954 - 1999	6.7	67
De Soto	1959 - 1999	6.7	67
Canoga Avenue	1954- 1960	-	67
Downey	1952 - 1956	-	67

a. Radionuclides assumed for consistency with the predominant ones used for internal dose calculation. Pu-239 is representative of alpha-emitting radionuclides, Sr-90 representative of beta/gamma-emitting radionuclides.

#### 4.8 UNCERTAINTY

Uncertainty is lower in more recent years and higher in earlier years when less data are available. There are few available documents with estimates of uncertainty for SSFL environmental measurements. No information is available on uncertainty of stack effluent concentrations. Many results are reported as less-than values, which indicates concentrations below the minimum detectable concentration. Qualitative estimates of inhalation intakes are 50% at 1 standard deviation from 1988 to 1999, 100% from 1971 to 1987, and 200% from 1959 to 1970.

Some of the best estimates of uncertainty are associated with the later years for external dose. Qualitative estimates of occupational environmental external dose are 20% at 1 standard deviation from 1996 to 1999; 50% from 1990 to 1995; 100% from 1975 to 1989; and 200% from 1959 to 1974.

Qualitative estimate of ingestion intakes are 100% at 1 standard deviation.

#### 4.9 ATTRIBUTIONS AND ANNOTATIONS

All information requiring identification was addressed via references integrated into the reference section of this document.

## REFERENCES

- AEC (U. S. Atomic Energy Commission), 1974, *Termination of Operating Licenses for Nuclear Reactors*, Regulatory Guide 1.86, Directorate of Regulatory Standards, Washington, D.C.
- ATSDR (Agency for Toxic Substances and Disease Registry), 1999, *Draft Preliminary Site Evaluation Santa Susanna Field Laboratory (SSFL), Ventura County California*, CERCLIS No. CAD074103771, [http://www.atsdr.cdc.gov/HAC/PHA/santa/san\\_toc.html](http://www.atsdr.cdc.gov/HAC/PHA/santa/san_toc.html), Division of Health Assessment and Consultation, ATSDR, Atlanta, Georgia.
- Boeing (The Boeing Company), 2000, *Site Environmental Report for Calendar Year 1999 DOE Operations at Rocketdyne Propulsion & Power*, RD00-159, Canoga Park, California. [SRDB Ref ID: 19127]
- Boeing (The Boeing Company), 2003, *Radiological Operations and Clean-up at the De Soto Facility*, Appendix B, Canoga Park, California, June 12. [SRDB Ref ID: 19145]
- Eggleston, R. R., 1983, *Annual Review of Radiological Controls – 1980*, Rockwell International, Energy Systems Group, Canoga Park, California, October 12. [SRDB Ref ID: 19132]
- Eggleston, R. R., 1984, *Annual Review of Radiological Controls – 1981*, Rockwell International, Energy Systems Group, Canoga Park, California, May 29. [SRDB Ref ID: 19131]
- Gaylord, G. G., 1990, "1989 Environmental Monitoring Report," memorandum to J. T. Davis (U.S. Department of Energy), April 11, Rockwell International, Rocketdyne Division, Canoga Park, California, April 11. [SRDB Ref ID: 15974]
- Hart, R. S., 1979, *Annual Review of Radiological Controls – 1975*, Rockwell International, Atomics International Division, Canoga Park, California, July 2. [SRDB Ref ID: 19137]
- Hart, R. S., 1980a, *Annual Review of Radiological Controls – 1976*, Rockwell International, Energy Systems Group, Canoga Park, California, April 28. [SRDB Ref ID: 19136]
- Hart, R. S., 1980b, *Annual Review of Radiological Controls – 1977*, Rockwell International, Energy Systems Group, Canoga Park, California, May 22. [SRDB Ref ID: 19135]
- Hart, R. S., 1980c, *Annual Review of Radiological Controls – 1978*, Rockwell International, Energy Systems Group, Canoga Park, California, August 6. [SRDB Ref ID: 19134]
- Hart, R. S., 1980d, *Annual Review of Radiological Controls – 1979*, Rockwell International, Energy Systems Group, Canoga Park, California, September 15. [SRDB Ref ID: 19133]
- Heine, W. F., 1973, "Evaluation of Dose to the Public Near AEC Facilities," memorandum to R. L. Westby, April 25, 1973, 73AT-2593, Atomics International, Canoga Park, California. [SRDB Ref ID: 19681]
- ICRP (International Commission on Radiological Protection), 1975, *Reference Man: Anatomical, Physiological and Metabolic Characteristics*, ICRP Publication 23, Pergamon Press, Oxford, England.
- Jobst, J. E., 1979, *Aerial Radiological Survey of Rockwell International Facilities, Canoga Park, California*, EGG-1183-1751, EG&G Energy Measurements Group, Las Vegas, Nevada. [SRDB Ref ID: 19051]

- Kennedy, W. E., Jr., D. L. Strenge, R. A. Meck, and C. Daily, 1992, *Residual Radioactive Material from Decommissioning, Technical Basis for Translating Contamination Levels to Annual Total Effective Dose Equivalent*, NUREG/CR-5512, PNL-7994, Pacific Northwest Laboratory, Richland, Washington. [SRDB Ref ID: 23558]
- Liddy, P. and P. Rutherford, 2001, *Radiation Survey of the Downey Facility*, RS-00019, The Boeing Company, Canoga Park, California, May 4. [SRDB Ref ID: 19180]
- Moore, J. D., W. L. Fisher, and P. A. Rowe, 1962, *Environmental Monitoring SemiAnnual Report January 1, 1962 to June 30, 1962* NAA-SR-7650, Atomics International, Canoga Park, California, November 30. [SRDB Ref ID: 19064]
- Moore, J. D., c. 1974, *Environmental and Radioactive Effluent Monitoring Annual Report 1973*, Atomics International, Canoga Park, California. [ETEC 35] [SRDB Ref ID: 19682]
- Moore, J. D., 1989, *Rocketdyne Division Environmental Monitoring and Facility Effluent Annual Report, De Soto and Santa Susana Field Laboratories Sites 1988*, RI/RD89-139, Rockwell International, Canoga Park, California. [SRDB Ref ID: 19119]
- NIOSH (National Institute for Occupational Safety and Health), 2002, *Internal Dose Reconstruction Implementation Guideline*, OCAS-IG-002, Rev. 0, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- NIOSH (National Institute for Occupational Safety and Health), 2007, *Radiation Exposures Covered for Dose Reconstructions Under Part B of the Energy Employees Occupational Illness Compensation Program Act*, OCAS-IG-003, Rev. 0, Office of Compensation Analysis and Support, Cincinnati, Ohio, November. [SRDB Ref ID: 35987]
- NIOSH (National Institute for Occupational Safety and Health), 2009, *Special Exposure Cohort, Petition Evaluation Report Petition SEC-00093*, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- NIOSH (National Institute for Occupational Safety and Health), 2010a, *Special Exposure Cohort, Petition Evaluation Report Petition SEC-00156*, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- NIOSH (National Institute for Occupational Safety and Health), 2010b, *Special Exposure Cohort, Petition Evaluation Report Petition SEC-00151*, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- NIOSH (National Institute for Occupational Safety and Health), 2010c, *Special Exposure Cohort, Petition Evaluation Report Petition SEC-00167*, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- NIOSH (National Institute for Occupational Safety and Health), 2010d, *Special Exposure Cohort, Petition Evaluation Report Petition SEC-00168*, Office of Compensation Analysis and Support, Cincinnati, Ohio.
- Oldenkamp, R. D. and J. C. Mills, 1991, *Nuclear Operations at Rockwell's Santa Susana Field Laboratory – A Factual Perspective*, N001ER000017, Revision C, Rockwell International, Canoga Park, California. [SRDB Ref ID: 20546]

- Remley, M. E., 1979, untitled memorandum to C. D. Jackson, 79ESG-1391, Rockwell International, Canoga Park, California, February 12. [SRDB Ref ID: 15988]
- Robinson, K. S., editor, 1998, *Rocketdyne Propulsion & Power DOE Operations Annual Site Environmental Report 1997*, A4CM-ZR-0012, The Boeing Company, Canoga Park, California. [SRDB Ref ID: 19125]
- Rockwell International, 1991, *Rocketdyne Division Environmental Monitoring Annual Report Santa Susana Field Laboratory, De Soto, and Canoga Sites 1990*, RI/RD91-136, Rockwell International, Canoga Park, California. [SRDB Ref ID: 19120]
- Rockwell International, 1992, *Rocketdyne Division Environmental Monitoring Annual Report Santa Susana Field Laboratory and De Soto Sites 1991*, RI/RD92-138, Rockwell International, Canoga Park, California. [SRDB Ref ID: 19121]
- Rockwell International, 1993, *Rocketdyne Division Environmental Monitoring Annual Report Santa Susana Field Laboratory and De Soto Sites 1992*, RI/RD93-125, Revision A, Rockwell International, Canoga Park, California. [SRDB Ref ID: 19122]
- Rockwell International, 1996, *Rocketdyne Division Environmental Monitoring Annual Report Santa Susana Field Laboratory and De Soto Sites 1995*, RI/RD96-140, Rockwell Aerospace, Canoga Park, California. [SRDB Ref ID: 19123]
- Rutherford, P. D, editor, 1999, Site Environmental Report for Calendar Year 1998 DOE Operations at Rocketdyne Propulsion & Power, RD99-115, The Boeing Company, Canoga Park, California. [SRDB Ref ID: 19126]
- Rutherford, P. D., 2002, *Historical Radiological Activities at Building 038 (Vanowen Building)*, January 15, The Boeing Company, Canoga Park, California. [SRDB Ref ID: 19179]
- Rutherford, P. D., 2005, "Sodium Reactor Experiment (SRE) Original Accident Release Data," memorandum to E. Crawford, January 21, 2005RC0202, The Boeing Company, Canoga Park, California. [SRDB Ref ID: 19161]
- Sapere Consulting, Inc., and The Boeing Company, 2005, *Historical Site Assessment of Area IV, Santa Susana Field Laboratory, Ventura County, California*, May, Santa Susana Field Laboratory Ventura County, California. [SRDB Ref ID: 20531]
- Sebelius, K., 2009, *HHS Designation of Additional Members of the Special Exposure Cohort under the Energy Employees Occupational Illness Compensation Program Act of 2000, Designating a Class of Employees from Santa Susana Field Laboratory – Area IV, Santa Susana, California*, U.S. Department of Health and Human Services, Office of the Secretary, Washington, D.C., June 18.
- Tuttle, R. J., 1985, *Annual Review of Radiological Controls – 1982*, Rockwell International, Energy Systems Group, Canoga Park, California, January 29. [SRDB Ref ID: 19130]
- Tuttle, R. J., 1986a, *Annual Review of Radiological Controls – 1983*, Rockwell International, Rocketdyne Division, Canoga Park, California, February 12. [SRDB Ref ID: 19129]
- Tuttle, R. J., 1986b, *Annual Review of Radiological Controls – 1984*, Rockwell International, Rocketdyne Division, Canoga Park, California, March 18. [SRDB Ref ID: 19128]

Tuttle, R. J., 1986c, *Annual Review of Radiological Controls – 1985*, Rockwell International, [SRDB Ref ID: 19142]

Rocketdyne Division, Canoga Park, California, July 11. [030005856] This file path leads to Tuttle, R. J., 1986c, *Annual Review of Radiological Controls – 1985*, Rockwell International, [SRDB Ref ID: 19142]

Tuttle, R. J., 1988a, *Annual Review of Radiological Controls – 1986*, Rockwell International, Rocketdyne Division, Canoga Park, California, July 5. [SRDB Ref ID: 19141]

Tuttle, R. J., 1988b, *Annual Review of Radiological Controls – 1987*, Rockwell International, Rocketdyne Division, Canoga Park, California, July 28. [SRDB Ref ID: 19140]

Tuttle, R. J., 1989, *Annual Review of Radiological Controls – 1988*, Rockwell International, Rocketdyne Division, Canoga Park, California, May 12. [SRDB Ref ID: 19139]

Tuttle, R. J., editor, 1997, *Rocketdyne Propulsion & Power DOE Operations Annual Site Environmental Report 1996*, RD97-134, The Boeing Company, Canoga Park, California. [SRDB Ref ID: 19124]

## GLOSSARY

### alpha radiation

Positively charged particle emitted from the nuclei of some radioactive elements. An alpha particle consists of two neutrons and two protons (a helium nucleus) and has an electrostatic charge of +2. Alpha particles have low-penetrating power and a short range (a few centimeters in air). Outside the body, the most energetic alpha particle generally fails to penetrate the dead layers of cells covering the skin or a sheet of paper. Alpha particles emitted by radionuclides inside the body are a more significant health risk.

### becquerel (Bq)

International System unit of radioactivity equal to 1 disintegration per second; 1 curie equals 37 billion ( $3.7 \times 10^{10}$ ) Bq.

### beta radiation

Charged particle emitted from some radioactive elements with a mass equal to 1/1,837 that of a proton. A negatively charged beta particle is identical to an electron. A positively charged beta particle is a positron. Most of the direct fission products are (negative) beta emitters. Exposure to large amounts of beta radiation from external sources can cause skin burns (erythema), and beta emitters can be harmful inside the body. Thin sheets of metal or plastic can stop beta particles.

### dosimetry

Measurement and calculation of internal and external radiation doses.

### exposure

(1) In general, the act of being exposed to ionizing radiation. (2) Measure of the ionization produced by X- and gamma-ray photons in air in units of roentgens.

### radioactivity

Disintegration of certain elements (e.g., radium, actinium, uranium, and thorium) accompanied by the emission of alpha, beta, gamma, and/or neutron radiation from unstable nuclei.

### rem

Traditional unit of radiation dose equivalent that indicates the biological damage caused by radiation equivalent to that caused by 1 rad of high-penetration X-rays multiplied by a quality factor. The average American receives 360 millirem a year from background radiation. The sievert is the International System unit; 1 rem equals 0.01 sievert. The word derives from roentgen equivalent in man; rem is also the plural.

### thermoluminescent dosimeter (TLD)

Device for measuring radiation dose that consists of a holder containing solid chips of material that, when heated by radiation, release the stored energy as light. The measurement of this light provides a measurement of absorbed dose.